



00131950

### Tensioning connector



- ▶ Tensioning connector for fast assembly
- ▶ The connector can be moved within the slot
- ▶ Easily accessible screws
- ▶ Three slots are left free for mounting surface elements
- ▶ Profile finishing: not required

Technical data (p. 19-8)

P			
30x...	1000 N	35 Nm	15 Nm
45x...L	3500 N	110 Nm	30 Nm
40x..., 45x..., 50x..., 90x...	3500 N	110 Nm	30 Nm
60x...	3500 N	195 Nm	60 Nm

Tensioning connector	Slot	P	ESD		No.
<b>8</b>	8	30x...		10	<b>3 842 538 489</b>
<b>10L</b>	10	45x...L		10	<b>3 842 538 491</b>
<b>10</b>	10	40x..., 45x..., 50x..., 60x..., 90x...		10	<b>3 842 538 490</b>

Material: steel; galvanized